


IMPORTANT FACT:
 WORN WORKING GAGE WILL REJECT
 CASTINGS THAT COULD BE PASSED.



VERIFICATION PROCESS:
 HOLD WORKING GAGE TIGHT AGAINST
 MASTER GAGE AS SHOWN AT SURFACE
 A OR B AND CHECK CLEARANCE AS SHOWN

Scale: .5X

WINCHESTER INDUSTRIES INC.

MASTER GAGE APPLICATION

SIZE A	Job#	DWG NO. W306A	Disk	REV A
CUSTOMER WINCHESTER			ENG JCD	12/5/95