

VERIFYING W600 & W601 USING MASTER GAGE W785A

MUST READ "2" ON FINGER
AT "0" ON GAGE BODY
WITH HEEL OF FINGER
RESTING ON GAGE

VERIFY LOCATION
WITNESS GROOVE NOTCH

MUST SEAT

"0" AT "0"
ALRIGHT TO BE SLIGHTLY ABOVE
REFLECTS UNUSED WEAR ALLOWANCE
REJECT IF "0" LINE OFF BODY

MUST SEAT

MUST NOT SEAT

MUST SEAT

NOTCH ALIGNS
WITH "12" LINE

MUST NOT SEAT

