



**The simplified steel gage or the combined gage can be used to check condemning limits as shown.**