



RECALIBRATION:

1. VISUALLY CHECK THE GAGE FOR DAMAGE.
2. USE A CALIBRATED SCALE TO VERIFY MEASURING GRADUATION ON THE MEASURING ROD.
3. VERIFY OVERALL LENGTH WITH MASTER GAGE W343

RECERTIFICATION TOLERANCE +/- .015"

REFERENCE:

AAR MANUAL OF STANDARDS AND RECOMMENDED PRACTICES  
 Back-to-Back Mounting Gage for All Steel Wheels  
 Rule 5.3  
 Figure 5.4  
 Section G-II

WINCHESTER INDUSTRIES INC.				
SIZE A	Job#	DWG NO. W783	Disk	REV E
CUSTOMER			ENG	PDT 08/22/2012