


MAXIMUM CLEARANCE
NEW GAGE - .010"
WORN LIMIT - .031"

MAXIMUM CLEARANCE
NEW GAGE - .010"
WORN LIMIT - .031"

IMPORTANT:
USER MAY ELECT TO SCRAP GAGE
BEFORE .031" LIMIT REACHED
AS GAGE WEARS - IT REJECTS MORE MATERIAL
THAT WOULD BE ACCEPTED BY NEW GAGE



VERIFICATION PROCEDURE FOR
GAGE 47120-2 (W681) USING
MASTER GAGE W307

Scale: .5X

WINCHESTER INDUSTRIES INC.

MASTER GAGE APPLICATION

SIZE A	Job#	DWG NO. W307A	Disk	REV A
-----------	------	------------------	------	----------

CUSTOMER WINCHESTER | ENG JCD 12/7/95