

REFERENCE:
CANADIAN PACIFIC DRAWING 60-C-343

VERIFICATION PROCEDURE

- 1. SEAT GAGE AS ILLUSTRATED
- 2. MEASURE CLEARANCE AT POINTS "A" THRU "H" WITH FEELER GAGE
- 3. MAXIMUM CLEARANCE NEW GAGE - .005" WEAR LIMIT - .015"

